
## IMPORTANT: READ ALL DIRECTIONS BEFORE STARTING

- Cut PCB etch with utility knife at Points "A", "B", "C", "D" & "E".
- Solder 24 AWG or larger wire between points "F" & "G".
- Solder handbox interface wires from CCD/Guide system to points 1 through 12. Use chart below for wire color location.

Handbox Interface Wires				
1 = 2 = 3 = 4 = 5 = 6 =	Gray Tan Pink Green Blue Orange		= = = = =	

4. Attach one end of four 5.6 Kilo OHM, 1/4 Watt resistor to points "3","6","9" & "12". Join the resistors at point "H". Point "H" is not connected to the board. "I" is simply a junction point. Solder 24 AWG or larger wire between points "H" & "I".

(Component Side)



(Solder Side)

Santa Barbara Instrument Group Santa Barbara, California 93108 LX-6 Hand Box Modification

Document Number

September 22, 1998

KG

Sheet 1 of 1

Instructions